



**INSTRUCTION MANUAL**  
**MT1003**  
**1000V AC/DC MULTIMETER**



**TRUERMS**



## Contents

## Page no

1. Introduction.....	5
2. Safety.....	5
2.1. Safety Instructions.....	6
3. Features.....	7
3.1. Understanding the push buttons.....	7
3.2. Meter Description.....	7
3.3. Understanding the Display.....	8
3.4. Understanding the Rotary Switch.....	8
3.5. Using the Input Terminals.....	9
4. Operation.....	9
4.1. AC Voltage Measurements.....	9
4.2. DC Voltage Measurements.....	10
4.3. AC + DC.....	10
4.4. mV Voltage Measurements.....	11
4.5. Frequency Measurements.....	11
4.6. Resistance Measurements.....	12
4.7. Continuity Check.....	12
4.8. Diode Check.....	13
4.9. Capacitance Measurements.....	13
4.10. Temperature Measurements.....	14
4.11. DC Current Measurements.....	14
4.12. AC Current Measurements.....	15
4.13. 4 - 20mA% Measurements.....	15
5. Understanding the Displays.....	15
5.1. Graph Measure.....	16
5.2. Capturing Minimum and Maximum Values.....	16
5.3. Capturing Peak Values.....	17
5.4. Relative Values.....	17
5.5. Hold Mode.....	17
5.6. Save Function.....	17
5.7. Storing Individual Measurements Data.....	17
5.8. Viewing Memory Data.....	18
5.9. Viewing Graph Data.....	18
5.10. Recording Measurement Data.....	18
5.11. Viewing Trend Data.....	18
5.12. Info.....	19
5.13. Setup Options.....	19
5.14. Resetting Meter.....	19

## Contents

## Page no

5.15. Meter Info.....	19
5.16. Setting Format.....	20
5.17. Setting Display.....	20
5.18. Setting Time and Date.....	20
5.19. Auto Power Off.....	20
5.20. Foreground and Background.....	20
5.21. Set Font.....	20
6. Replacing the Batteries.....	21
7. Replacing the Fuses.....	21
8. Li-ion Battery Charge.....	22
9. Functions.....	23
10. Specifications.....	23
10.1. AC Voltage.....	24
10.2. DC Voltage.....	24
10.3. AC + DC.....	24
10.4. Resistance.....	24
10.5. Temperature (Type-K).....	25
10.6. DC Current.....	25
10.7. AC Current.....	25
10.8. Capacitance.....	25
10.9. Frequency (electronic).....	26
10.10. Frequency.....	26
10.11. Duty Cycle (electrical).....	26

## 1. INTRODUCTION

The MT1003 Heavy duty True RMS Industrial Digital Multimeter with TFT colour LCD display, provides fast A/D converting sampling time, high accuracy, built-in data logging and Trend Capture features. It can trace any interruptions of the equipment and record events automatically unattended. Using this meter, it is easy to find and solve the problems while the internal memory keeps measurements stored. This meter provides safer measurements with the double moulded rubber housing design.

## 2. SAFETY



This symbol adjacent to another symbol, terminal or operating device indicates that the operator must refer to an explanation in the Operating Instructions to avoid personal injury or damage to the meter.



This symbol adjacent to one or more terminals identifies them as being associated with ranges that may, in normal use, be subjected to particularly hazardous voltages. For maximum safety, the meter and its test leads should not be handled when these terminals are energized.



Equipment is protected by double or reinforced insulation



This symbol advises the user that the terminal(s) so marked must not be connected to a circuit point at which the voltage with respect to earth ground exceeds (in this case) 1000 VAC or VDC.



This **WARNING** symbol indicates a potentially hazardous situation, which if not avoided, could result in death or serious injury.



This **CAUTION** symbol indicates a potentially hazardous situation, which if not avoided, may result in damage to the product.

## PER IEC1010 OVERVOLTAGE INSTALLATION CATEGORY OVERVOLTAGE CATEGORY I

Equipment of **OVERVOLTAGE CATEGORY I** is equipment for connection to circuits in which measures are taken to limit the transient overvoltages to an appropriate low level.

**Note:** Examples include protected electronic circuits.

## OVERVOLTAGE CATEGORY II

Equipment of **OVERVOLTAGE CATEGORY II** is energy-consuming equipment to be supplied from the fixed installation.

**Note:** Examples include household, office, and laboratory appliances.

## OVERVOLTAGE CATEGORY III

Equipment of **OVERVOLTAGE CATEGORY III** is equipment in fixed installations.

**Note:** Examples include switches in a fixed installation and some equipment for industrial use with a permanent connection to the fixed installation.

## OVERVOLTAGE CATEGORY IV

Equipment of **OVERVOLTAGE CATEGORY IV** is for use at the origin of the installation.

**Note:** Examples include electricity meters and primary over-current protection equipment

### 2.1. Safety Instructions

This meter has been designed for safe use, but must be operated with caution. The rules listed below must be carefully followed for safe operation.

**NEVER** apply voltage or current to the meter that exceeds the specified maximum:

Function	Maximum Input
V DC or VA C	1000V DC/AC RMS
mA AC/DC	800mA 1000V fast acting fuse
A AC/DC	10A 1000V fast acting fuse (20A for 30 seconds max every 10 minutes)
Frequency, Resistance, capacitance, Duty Cycle, Diode Test, Continuity	1000V DC/AC RMS
Temperature	1000V DC/AC RMS
Surge Protection: 8kV peak per IEC 61010	

**USE EXTREME CAUTION** when working with high voltages.

**DO NOT** measure voltage if the voltage on the "COM" input jack exceeds 1000V above earth ground.

**NEVER** connect the meter leads across a voltage source while the function switch is in the current, resistance, or diode mode. Doing so can damage the meter.

**ALWAYS** discharge filter capacitors in power supplies and disconnect the power when making resistance or diode tests.

**ALWAYS** turn off the power and disconnect the test leads before opening the covers to replace the fuse or batteries.

**NEVER** operate the meter unless the back cover and the battery and fuse covers are in place and fastened securely. If the equipment is used in a manner not specified by the manufacturer, the protection provided by the equipment may be impaired.


### 3. FEATURES

#### 3.1. Understanding the Push Buttons

The 6 push buttons on the front of the Meter activate features that augment the function selected using the rotary switch, navigate menus or control power to Meter circuits.


#### 3.2. Meter Description

- 1 - **F1** button, Default switch to Graph measure.
- 2 - **F2** button, Default modes related to the rotary switch function.
- 3 - **F3** button, Default into save mode, default display and wake up for APO.
- 4 - **F4** button, Default modes **MIN/MAX** starts and stops **MIN/MAX** recording.
- 5 - **RANGE**, Into manual range and select range of the measurement. When Pressing the **RANGE** button for more than 1 second the instrument will return to **AUTO RANGE**.
- 6 - **HOLD/REL**, Freezes the present reading on the display and allows the display to be saved. If Pressing the **HOLD/REL** button for more than 1 second will switch to **RELATIVE MODE**.



### 3.3. Understanding the Display


- 1 - Labels on the LCD display indicate the function of the button just below the displayed label.
- 2 - Analog bargraph display of the input signal.
- 3 - Minus sign Indicates a negative reading.
- 4 - Displays measurement information about the input signal.
- 5 - Indicates the range the Meter is in and the ranging mode (auto or manual)
- 6 - Indicates the time set in the internal clock.
- 7 - Indicates the Meter's beeper is enabled (not associated with the continuity beeper).
- 8 - Indicates the charge level of the batteries
- 9 - Indicates the units of measure.



### 3.4. Understanding the Rotary Switch

Select a primary measurement function by positioning the rotary switch to one of the icons around its perimeter. For each function, the Meter presents a standard display for that function (range, measurement units, and modifiers). Button choices made in one function do not carry over into another function.

<b>V~</b>	AC voltage measurements.
<b>V-</b>	DC and AC+DC voltage measurements.
<b>mV</b>	DC(AC) milli-volts measurements.
<b><math>\Omega</math> <math>\rightarrow</math> <math>\nabla</math> CAP</b>	Resistance, Diode test, Capacitance and Continuity Measurements.
<b>Hz%</b>	Frequency measurements.
<b>Temp</b>	Temperature measurements.
<b>A</b>	AC, DC amps measurements.
<b>mA</b>	AC, DC milliamps measurements.
<b>4-20 mA%</b>	% 4-20MA measurements.
<b><math>\mu</math>A</b>	AC, DC microampere measurements up to 5,000 $\mu$ A.







## 4.2. DC Voltage Measurements


**CAUTION:** Do not measure **DC** voltages if a motor on the circuit is being switched **ON or OFF**. Large voltage surges may occur that can damage the meter.

1. Set the function switch to the yellow **VDC** position.
2. Insert the black test lead banana plug into the negative **COM** jack. Insert the red test lead banana plug into the positive **V** jack.
3. Read the Voltage in the display.



## 4.3. AC + DC

1. Set the function switch to the yellow **VDC** position.
2. Insert the black test lead banana plug into the negative **COM** jack. Insert the red test lead banana plug into the positive jack.
3. Press the **MODE** key to indicate "AC + DC" on the display.
4. Read AC + DC measurement value in the display.



#### 4.4. mV Voltage Measurements

**CAUTION:** Do not measure **mV** voltages if a motor on the circuit is being switched **ON** or **OFF**. Large voltage surges may occur that can damage the meter.

1. Set the function switch to the yellow **mV** position.
2. Press the **MODE** key. Switch to **mVDC (mVAC)**.
3. Insert the black test lead banana plug into the negative **COM** jack. Insert the red test lead banana plug into the positive **V** jack.
4. Read the **mV** voltage in the display



#### 4.5. Frequency Measurements

1. Set the function switch to the yellow **Hz%** position.
2. Insert the black test lead banana plug into the negative **COM** jack. Insert the red test lead banana plug into the positive **V** jack.
3. Read the Frequency in the display.



#### 4.6. Resistance Measurements

**WARNING:** To avoid electric shock, disconnect power to the unit under test and discharge all capacitors before taking any resistance measurements

Remove the batteries and unplug the line cords.

1. Set the function switch to the yellow  $\Omega$  CAP  $\rightarrow$   $\gg$  position.
2. Insert the black test lead banana plug into the negative **COM** jack. Insert the red test lead banana plug into the positive  $\Omega$  Jack.
3. Read the resistance in the display.



#### 4.7. Continuity Check


**WARNING:** To avoid electric shock, disconnect power to the unit under test and discharge all capacitors before taking any resistance measurements. Remove the batteries and unplug the line cords.

1. Set the function switch to the yellow  $\Omega$  CAP  $\rightarrow$   $\gg$  position.
2. Press the **MODE** key. Switch to Conductance.
3. Insert the black test lead banana plug into the negative **COM** jack. Insert the red test lead banana plug into the positive jack.
4. If the resistance is less than approximately **50Ω**, the audible signal will sound. If the circuit is open, the display will indicate "**OL**".



#### 4.8. Diode Test


1. Set the function switch to the yellow  $\Omega$  CAP  $\rightarrow$   $\rightarrow$  position.
2. Press the **MODE** key. Switch to Diode.
3. Insert the black test lead banana plug into the negative **COM** jack and the red test lead banana plug into the positive **V** jack.
4. Forward voltage will typically indicate 0.400 to 3.200V. Reverse voltage will indicate "OL". Shorted devices will indicate near 0V and an open device will indicate "OL" in both polarities.



#### 4.9. Capacitance Measurements

**WARNING:** To avoid electric shock, disconnect power to the unit under test and discharge all capacitors before taking any capacitance measurements. Remove the batteries and unplug the line cords.

1. Set the rotary function switch to the yellow  $\Omega$  CAP  $\rightarrow$   $\rightarrow$  position.
2. Press the **MODE** key. Switch to **CAP**.
3. Insert the black test lead banana plug into the negative **COM** jack. Insert the red test lead banana plug into the positive **V** jack.
4. Read the Capacitance value in the display.



#### 4.10. Temperature Measurements

1. Set the function switch to the yellow **TEMP** ( $^{\circ}\text{C}$  or  $^{\circ}\text{F}$ ) position.
2. Press the **MODE** key.  
Switch to **TEMP** ( $^{\circ}\text{C}$  or  $^{\circ}\text{F}$ ).
3. Insert the Temperature Probe into the input jacks, making sure to observe the correct polarity.
4. Read the temperature in the display



#### 4.11. DC Current Measurements

**CAUTION:** Do not make **20A** current measurements for longer than 30 seconds. Exceeding 30 seconds may cause damage to the meter and/or the test leads.


1. Insert the black test lead banana plug into the negative **COM** jack.
2. For current measurements up to  $6000\mu\text{A}$  DC, set the function switch to the yellow  **$\mu\text{A}$**  position and insert the red test lead banana plug into the  **$\mu\text{A}/\text{mA}$**  jack.
3. For current measurements up to  $600\text{mA}$  DC, set the function switch to the yellow **mA** position and insert the red test lead banana plug into the  **$\mu\text{A}/\text{mA}$**  jack.
4. For current measurements up to  $10\text{A}$  DC, set the function switch to the yellow **10A** position and insert the red test lead banana plug into the **10A** jack.
5. Press the **MODE** key to indicate "DC" on the display.
6. Read the current in the display.



#### 4.12. AC Current Measurements

**CAUTION:** Do not make **10A** current measurements for longer than 30 seconds. Exceeding 30 seconds may cause damage to the meter and/or the test leads.


1. Insert the black test lead banana plug into the negative **COM** jack.
2. For current measurements up to  $6000\mu\text{A}$  AC, set the function switch to the yellow  **$\mu\text{A}$**  position and insert the red test lead banana plug into the  **$\mu\text{A}/\text{mA}$**  jack.
3. For current measurements up to  $600\text{mA}$  AC, set the function switch to the yellow  **$\text{mA}$**  position and insert the red test lead banana plug into the  **$\mu\text{A}/\text{mA}$**  jack.
4. For current measurements up to  $10\text{A}$  AC, set the function switch to the yellow  **$10\text{A}$**  position and insert the red test lead banana plug into the  **$10\text{A}$**  jack.
5. Press the **MODE** key to indicate "AC" on the display.
6. Read the current in the display.



#### 4.13. 4 — 20mA% Measurements

1. Set up and connect as described for DC mA measurements.
2. Set the rotary function switch to the **4-20mA%** position.
3. The meter will display loop current as a % with  $0\text{mA} = -25\%$ ,  $4\text{mA} = 0\%$ ,  $20\text{mA} = 100\%$ , and  $24\text{mA} = 125\%$ .



#### 5. UNDERSTANDING THE DISPLAYS



### 5.1. Graph Measure


1. Press **Graph (F1)** key, the meter will switch to Graph measure.
2. Press the **START** key.
3. Press the **FAST** or **SLOW** key to adjust the sampling rate.
4. Press the **CANCEL** key to exit Graph and return to normal measurement mode

Press the **STOP** key.



Press the **SAVE** key to save the Graph.


Press the **BACK** key to return.



### 5.2. Capturing Minimum and Maximum Values

To activate the **MAX/MIN** mode, Press **MIN/MAX(F4)** key, at the measurement mode.

As shown in the Figure, the Meter displays at the top of the measurement page, the **MAX/MIN** start date and the amount of time at the bottom of the page. In addition, the recorded maximum, average, and minimum values appear in the secondary display with their respective elapsed times.



To stop a **MIN/MAX** recording session, press the **STOP** key.

The summary information in the display freezes, and the label function




changes to allow saving the collected data. Pressing the **CLOSE** key exits the **MIN/MAX** record session without saving the collected data.

To save the **MIN/MAX** screen data, the **MIN/MAX** session must be ended by pressing the **STOP** key. Next, press the **SAVE** key.


### 5.3. Capturing Peak Values

To activate the peak mode, at AC measure **MIN/MAX** mode, Press the **PMAX(F4)** button.



### 5.4. Relative Values


To activate the relative mode, Press the **HOLD/REL** button for more than 1 second.



### 5.5. Hold Mode


To freeze the display for any function, press the **HOLD** button.

Press the **SAVE** key to save to memory. Press the **CLOSE** key to return to measurement.



### 5.6. Save Function

Press the **SAVE(F3)** key to enter the save menu.



### 5.7. Storing Individual Measurement Data


For common measurement functions, a snapshot of the screen data is saved by pressing the **SAVE** key. Then press the **DOWN(F3)** key to save the selected item, press the **ENTER(F1)** key.

## 5.8. Viewing Memory Data

Viewing data stored in the Meter's memory is performed through the **SAVE** menu. Press the **DOWN (F3)** key.

Position the menu selector next to the menu item labeled **ViewM**.

Press the **ENTER(F1)** key.




## 5.9. Viewing Graph Data


Viewing data stored in the Meter's memory is performed through the **SAVE** menu. Press the **DOWN (F3)** key.

Position the menu selector next to the menu item labeled **Graph**.

Press the **ENTER(F1)** key.




Press the « and » keys to move cursor.



## 5.10. Recording Measurement Data

Press the **SAVE** key.

Then press the **DOWN (F3)** key to **Record** the selected item, press the **ENTER(F1)** key. Press the **START** key to start recording. The recording session will continue until the allocated memory is used, the batteries expire, the rotary switch is moved. The session is terminated by pressing the **STOP** key.




## 5.11. Viewing Trend Data


Viewing data stored in the Meter's memory is performed through the **SAVE** menu.

Press the **DOWN (F3)** key. Position the menu selector next to the menu item labeled **ViewR** and press the **ENTER(F1)** key.

Press the **TREND(F1)** key.




Press the **+** key to increase Graph resolution.  
Press the **»** keys to move cursor.




### 5.12. Info

Viewing data stored in the Meter's memory is performed through the **SAVE** menu. Press the **DOWN (F3)** key. Position the menu selector next to the menu item labeled **INFO** and press the **ENTER(F1)** key.



### 5.13. Setup Options

Viewing data stored in the Meter's memory is performed through the **SAVE** menu. Press the **DOWN (F3)** key. Position the menu selector next to the menu item labeled **SETUP** and press the **ENTER(F1)** key.



### 5.14. Resetting Meter


The Meter's setup options can be reset to default values through the setup menu. Open the **setup** menu. Position the menu selector next to the menu item labeled **RESET** and press the **ENTER** key. Then Position the menu selector next to the menu item labeled **SETUP** and press the **OK** key. A message will appear asking to confirm the reset action. Press the **OK** key to perform the reset.

### 5.15. Meter Info

The Meter Info selection lists the serial number and firmware version. Open the setup menu. Position the menu selector next to the menu item labeled **METER INFO** and press the **ENTER** key.


### 5.16. Setting Format

Open the setup menu. Position the menu selector next to the menu item labeled **FORMAT** and press the **ENTER** key. Using the cursor buttons, move the menu selector next to the menu item labeled **Numeric(Date\Time)** format, press the **EDIT** key to edit, select 0.0000(0,0000), MM/DD/YY(DD/MM/YY) and 24 HOUR(12 HOUR) format.



### 5.17. Setting Display

Open the setup menu. Position the menu selector next to the menu item labeled **DISPLAY** and press the **ENTER** key.



### 5.18. Setting Date and Time

Open the setup menu. Position the menu selector next to the menu item labeled **DISPLAY** and press the **ENTER** key. Next, position the menu selector either next to the **Set Date** item or **Set Time** item and press the **EDIT** key.

### 5.19. Auto Power Off

Open the setup menu. Position the menu selector next to the menu item labeled **DISPLAY** and press the **ENTER** key. Then Position the menu selector next to the menu item labeled **POWER OFF** and press the **EDIT** key. To set **AUTO POWER OFF**. Use **UP** and **DOWN** to adjust the time to one of the preset values. 0 is disable the timeout feature. Press the **OK** key to set the selected time. Press the **CLOSE** key to return.

### 5.20. Foreground and Background

Open the setup menu. Position the menu selector next to the menu item labeled **DISPLAY** and press the **ENTER** key. Then Position the menu selector next to the menu item labeled **FOREGROUND AND BACKGROUND** and press the **OK** key. Use **UP** and **DOWN** to adjust.

### 5.21. Set Font

Open the setup menu. Position the menu selector next to the menu item labeled **DISPLAY** and press the **ENTER** key. Then Position the menu selector next to the menu item labeled **SELECT FONT** and press the **EDIT** key. Use **UP** and **DOWN** to adjust.

## 6. REPLACING THE BATTERIES


Refer to Figure and replace the batteries as follows:

1. Turn the Meter off and remove the test leads from the terminals.
2. Remove the battery door assembly by using a flat end screwdriver to turn the battery door screw one-half turn counterclockwise.
3. Replace the battery with 7.4V charge battery. Observe proper polarity.
4. Reinstall the battery door assembly and secure it by turning the screw one-half turn clockwise.

## 7. REPLACING THE FUSES


Refer to Figure, examine or replace the Meter's fuses as follows:

1. Turn the Meter off and remove the test leads from the terminals.
2. Remove the battery door assembly by using a flat end screwdriver to turn the battery door screw one-half turn counterclockwise.
3. Remove the fuse by gently prying one end loose, then sliding the fuse out of its bracket.
4. Install only specified replacement fuses.
5. Reinstall the battery door assembly and secure it by turning the screw one-half turn clockwise




## 8. LI-ION BATTERY CHARGE

1. Set the function switch to the **OFF/CHG** position.
2. Insert the socket into the Meter Input port, and connect the Adapter to the switch socket. Then Insert the Adapter into a Power socket.
3. A charge symbol will be displayed on the TFT color LCD display.



Enclosure	Double molded, waterproof
Shock (Drop Test)	2 meters (6.5 feet)
Diode Test	Test current of 1.5mA maximum, open circuit voltage 3.2V DC typical
Continuity Check	Audible signal will sound if the resistance is less than 50 $\Omega$ (approx.), test current <0.35mA
PEAK	Captures peaks >1ms
Temperature Sensor	Requires type K thermocouple
Input Impedance	>10M $\Omega$ VDC & >9M $\Omega$ VAC
AC Response	True RMS

## 9. FUNCTIONS

AC True RMS	The term stands for "Root-Mean-Square," which represents the method of calculation of the voltage or current value. Average responding multimeters are calibrated to read correctly only on sine waves and they will read inaccurately on non-sine wave or distorted signals. True RMS meters read accurately on either type of signal.
ACV Bandwidth	50Hz to 1000Hz
Display	6,000 count TFT LCD
Overrange indication	"OL" is displayed
Auto Power Off	5-30minutes (approximately) with disable feature
Polarity	Automatic (no indication for positive); Minus (-) sign for negative
Measurement Rate	3 times per second, nominal
Low Battery Indication	"  " is displayed if battery voltage drops below operating voltage
Battery	One 7.2V Li-ion battery
Fuses	mA, $\mu$ A ranges; 0.8A/1000V ceramic fast blow. A range; 10A/1000V ceramic fast blow
Operating Temperature	5°C to 40°C (41°F to 104°F)
Storage Temperature	-20°C to 60°C (-4°F to 140°F)
Operating Humidity	Max 80% up to 87°F (31°C) decreasing linearly to 50% at 40°C (104°F)
Storage Humidity	50% at 40°C (104°F)
Operating Altitude	<80% 2000 meters (7000ft.) maximum.
Safety	This meter is intended for origin of installation use and protected by double insulation per EN61010-1 and IEC61010-1 2nd Edition (2001) to Category IV 600V and Category III 1000V; Pollution Degree 2. The meter also meets UL 61010-1, 2nd Edition (2004), CAN/CSA C22.2 No. 61010-1 2nd Edition(2004), and UL61010B-2-031, 1st Edition (2003)

## 10. SPECIFICATIONS

### 10.1. AC Voltage

Range	Resolution	50/60Hz	<1kHz
600mV	0.1mV	±0.9%+5	±3.0%+5
6V	0.001V		
60V	0.01V		
600V	0.1V		
1000V	1V		

[1] upper 10% of range

### 10.2. DC Voltage

Range	Resolution	Accuracy
600mV [1]	0.1mV	(0.1 % + 5 digits)
6V	0.001V	
60V	0.01V	
600V	0.1V	(0.7% + 5 digits)
1000V	1V	(0.2% + 5 digits)

[1] when using the relative mode (REL Q) to compensate for offset

### 10.3. (AC + DC)

Range	Resolution	<1kHz
6V	0.001V	(3.0% + 20)
60V	0.01V	
600V	0.1V	
1000V	1V	

### 10.4. Resistance

Range	Resolution	Accuracy
600Ω[1]	0.1Ω	0.80% + 10
6kΩ	0.001kΩ	0.80% + 5
60kΩ	0.01kΩ	
600kΩ	0.1kΩ	
6MΩ	0.001MΩ	
60MΩ	0.01MΩ	2.5% + 10

[1] When using the relative mode (REL Q) to compensate for offsets.



## 10.5. Temperature (Type-K)

Range	Resolution	Accuracy
-40 to 1350°C	0.1°C	$\pm (1.2\% \text{ reading} + 3.0^\circ\text{C})$ $\pm (1.2\% \text{ reading} + 5.4^\circ\text{C})$ (probe accuracy not included)

1. Does not include thermocouple probe error.
2. Accuracy specification assumes ambient temperature stable to  $\pm 1^\circ\text{C}$ .
3. When in use for a long period of time, the reading will increase  $2^\circ\text{C}$

## 10.6. DC Current

Range	Resolution	Accuracy
600 $\mu\text{A}$	0.1 $\mu\text{A}$	$\pm 0.9\% + 5$
6000 $\mu\text{A}$	1 $\mu\text{A}$	
60mA	0.01mA	
600mA	0.1mA	$\pm 0.9\% + 8$
10A	0.01A	$\pm 1.5\% + 8$

## 10.7. AC Current

Range	Resolution	<1KHZ
600 $\mu\text{A}$	0.1 $\mu\text{A}$	$\pm (1.2\% + 5)$
6000 $\mu\text{A}$	1 $\mu\text{A}$	
60mA	0.01mA	
600mA	0.1mA	
10A	0.01A	$\pm (1.5\% + 5)$

(20A: 30 sec max with reduced accuracy)

All AC current ranges are specified from 5% of the range to 100% of range

## 10.8. Capacitance

Range	Resolution	Accuracy
60nF[1]	0.01nF	$\pm (1.5\% + 20)$
600nF	0.1nF	$\pm (1.2\% + 8)$
6 $\mu\text{F}$	0.001nF	$\pm (1.5\% + 8)$
60 $\mu\text{F}$	0.01 $\mu\text{F}$	$\pm (1.2\% + 8)$
600 $\mu\text{F}$	0.1 $\mu\text{F}$	$\pm (1.5\% + 8)$
6000 $\mu\text{F}$	0.01mF	$\pm (2.5\% + 20)$

[1] With a film capacitor or better, using relative mode (REL Q) to compensate for offsets.

### 10.9. Frequency (electronic)

Range	Resolution	Accuracy
60Hz	0.01Hz	$\pm(0.09\% + 5)$
600Hz	0.1Hz	
6kHz	0.001kHz	
60kHz	0.01kHz	
600kHz	0.1kHz	
10MHz	0.001MHz	

Sensitivity: 2V RMS min. @ 20% to 80% duty cycle and <100kHz; 5V RMS min @ 20% to 80% duty cycle and >100kHz


### 10.10. Frequency

Range	Resolution	Accuracy
40.00Hz - 10kHz	0.01Hz - 0.001kHz	$\pm(0.5\% \text{ reading})$

### 10.11. Duty Cycle (electrical)

Range	Resolution	Accuracy
0.1 to 99.90%	0.01%	Sensitivity: 2V <sub>rm</sub> $\pm(1.2\% \text{ reading} + 2 \text{ digits})$

Pulse width: 100 $\mu$ s - 100ms, Frequency: 5Hz to 10kHz





---

## ***MAJOR TECH (PTY) LTD***

**South Africa**

🌐 [www.major-tech.com](http://www.major-tech.com)

✉ [sales@major-tech.com](mailto:sales@major-tech.com)

**Australia**

🌐 [www.majortech.com.au](http://www.majortech.com.au)

✉ [info@majortech.com.au](mailto:info@majortech.com.au)

