

Measuring WITH KYORITSU



K2001

MINI CLAMP & MULTIMETER

Ø10mm Open Clamp Jaw
100A AC/DC
600V AC/DC
CAT II 600V



K3007IS

INTRINSICALLY SAFE DIGITAL INSULATION TESTER

3 test ranges 250V-500V-1000V
Auto null function
Trac-Lok mode
Live circuit warning



K3131IS

INTRINSICALLY SAFE DIGITAL INSULATION TESTER

3 test ranges 250V-500V-1000V
Auto null function
Trac-Lok mode
Live circuit warning



K3121

HV ANALOGUE INSULATION TESTER

Insulation Resistance 2.5kV
Large analogue display
Automatic discharge after test



Measuring WITH KYORITSU



K3122

HV ANALOGUE INSULATION TESTER

Insulation Resistance 5kV
Large analogue display
Automatic discharge after test

K3123

HV ANALOGUE INSULATION TESTER

Insulation Resistance 5kV and 10kV
Large analogue display
Automatic discharge after test



K3125

HV DIGITAL INSULATION TESTER

Wide Test Voltage from 250V to 5kV
Polarization index measurement (PI)
Insulation resistance up to 1000GΩ
Withstand Voltage test up to 5320V

K3128

HV DIGITAL INSULATION TESTER

Insulation Resistance (IR) & Leak Current with a wide range from 500V - 1kV - 2.5kV - 5kV - 10kV - 12kV
Polarization Index (PI)
Dielectric Absorption Ratio (DAR)
PC Software



Measuring WITH KYORITSU



K2009R

CLAMP METER

Ø55mm Cable Clamp size
2000A AC/DC
1000V DC / 750V AC
CAT IV 600V



K4140

LOOP IMPEDANCE, PFC & PSC TESTER

Anti-Trip Technology for complete trip free Loop testing on all RCD's rated 30mA and above
Dual display allows simultaneous measurements like Loop & PFC/PSC.
Two wire connections for Loop L-L, L-N and PSC testing is possible.

K8031F

PHASE ROTATION METER

Rotary disc indication
Can check a wide range of 3-phase power source from 110V to 600V AC
Checks phase sequence and open phase simultaneously



K4202

EARTH RESISTANCE CLAMP METER

Jaw Ø32mm
Earth / Ground Resistance 0.05Ω to 1500Ω resolution
True RMS readings
Bluetooth

Measuring WITH KYORITSU



K4118

LOOP IMPEDANCE AND PSC TESTER

Automatic Lock-Out if Test Resistor Overheats
Direct readout of Prospective Short
Circuit Current and Earth Fault Current
Measures low loop impedance of 0.01Ω

K4106

EARTH RESISTIVITY AND RESISTANCE TESTER

High test current up to 80mA yielding resolution of 0.001Ω on 2Ω range.

Earth resistance measurement with 4, 3 and 2 wires

Earth resistivity tester (ρ) using 4 pole Wenner method

800 Data storage points



K5410IS

INTRINSICALLY SAFE RCD/ELCB TESTER

Microprocessor controlled
Operating voltage 80V – 450V L-E

Auto Ramp

0° or 180° Phase angle selection

Rated current 10mA – 500mA

K8035

NON-CONTACT SAFETY PHASE INDICATOR

The insulated crocodile clips can clip insulated cables from $\Phi 2.4$ to 30mm

Measuring range for 3 phase installations from 70V to 1000V AC

CAT IV 600V

